SFFP 100% Made in Fra	Product present	ation (nu	in us on tagram	email : <u>info@cfpflex.com</u> site : <u>www.cfpflex.com</u> Date: 16/05/2	VEGAN
PRODUCT	UNIFLEX [®] <i>H</i> Sparkles Special effects		Plotter film with a sparkling effect for heat transfer on textiles		
CODES	111SP, 125SP, 101SP, 195SP, 116SP, 121SP, 124SP		COLOURS	Fuchsia, gold, black, red, blue, green, silver	
DESCRIPTION	Water based polyurethane coating, with sparkling effect, laminated between a non-adhesive polyester carrier and a heat adhesive layer.				
THICKNESS (+/-5%)	Heatadhesive polyurethane: 60 microns. Non-adhesive Carrier film: 100 microns.) microns.
TEXTILES	Cotton - Polyester - Polycotton				
ADVANTAGES	 Quick weeding Quick pressing time at low temperature: 140°C/10 seconds on cotton, polyester, polycotton Universal thermoadhesive with excellent bonding on most textiles. Washing resistance: cold wash Elastic and strong polyurethane, doesn't wrinkle after washings. Pleasant non-adhesive carrier, easy to stack and handle. Ecofriendly, water based, solvent and PVC free polyurethane. Low carbon profile manufacturing: all operations made under one roof. Hundred per cent made in France, out of european raw materials. Last generation machines and exclusive manufacturing process, ensuring competitive prices. 				
PRESSURE		Medium (depending upon the characteristics of the press)			
PEELING		COLDPEEL			
HEATPRESSING:		140°C/10 seconds			
WITHOUT OVERLAPPING		Washing temperature: cold wash			
2. Alwa baking FURTHER 3. Wait RECOMMANDATIONS 4. Do n 5. Iron		2. Always protect Flex baking paper, in order 3. Wait 24 hours befor 4. Do not use bleach of 5. Iron from inside.			
SAFETY Inert componen			ucts in a tempered and dry room, protected from direct sun rays. s, REACH compliant, without PVC, plastifiers, VOC, according lard 100 Class 1.		
		UNIFLEX SPARKLES can be applied on sublimated polyester. It blocks colors migration from the textile			
IRON ON After mirror cutting or text directly on g Peel off carrier whe		After mirror cutting wi or text directly on garr Peel off carrier when c	with scissors or by plotter, and weeding of contours, place the image rment, set the iron on medium heat. Don't use any vapour.		